OUT 51133

Cin. 2

FOR DI, BRASS KNOB.

PRIORITY

14 MAY EST

P 132000Z

FM CIA WASHDC

TO RUCSBR/SAC OFFUTT AFB OMAHA NEB

RUCVSM/4040TH SRW, LAUGHLIN AFT, TEXAS

RUEAHQ/DIAXX

RUECYG/NAVY PIC

DA GRNC

BT

S E C R E T

CITE CIA-Z-588



CENTER.
SUBJECT: FILM EVALUATION MISSION 3596 AND 3595.

- 1. MISSION 3596, FLOWN 11 MAY 1963 WITH CAMERA NO. 11 AND PROCESSED BY LAUGHLIN AFB SHOWED GOOD RESOLUTION AND EXPOSURE. NO CAMERA MALFUNCTIONS WERE OBSERVED. PROCESSING OF ORIGINAL NEGATIVE WAS POOR; I.E. WATER MARKS, SCRATCHES AND ABRASIONS WERE NOTED THROUGHOUT THE MISSION. DUPLICATE POSITIVE WAS OF LOW CONTRAST AND HAD A FLAT APPEARANCE.
- 2. MISSION 3595, FLOWN 10 MAY 1963, WITH CAMERA NO. 8 AND PROCESSED BY NAVY PIC SHOWED POOR TO GOOD RESOLUTION AND ADEQUATE EXPOSURE. POOR IMAGE QUALITY WAS NOTED ON NUMEROUS FRAMES PROBABLY DUE TO VEHICLE ATTITUDE, CDATA SHEET DID INDICATE AUTO-PILOT DIFFICULTIES). NO PROCESSING OR CAMERA MALFUNCTIONS WERE NOTED. DUPLICATE POSITIVE GOOD.

END OF MESSAGE

FROM NATIONAL PHOTOGRAPHIC INTERPRETATIONFILE

25

Declassification Review by NGA/DoD

GROUP 1
Excluded from automatic
foragrading and
desiresification

eredet